CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20223080

Address: 4408 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Failed Wednesday, March 08,

Residential 2023

Corrective Action Required:

1 Misc

- Install handrail at lower portion of basement stairs , handrail needs to extend nosing of last tread and return to wall.

other items that need corrected-

single wall flue to water heater is in contact with pex water line at

foundation wall. provide correct clearance.

- open junction box ceiling left of the furnace, provide outlet and coverer

plate.

Comments: