CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20223894Address:1046 SW FIORD DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Friday, March 31, 2023

Corrective Action Required:

concern	e neuon neganea.			
1 Misc		 Over notched stud at sill double garage wall 		
		 Fb upward penetration both sides of double garage door 		
		 Anchor at single garage plate break 		
		 Complete plumbing to second floor tub above single garage bay and five 		
		block floor		
		 Fire block HVAC chases top and bottom in garage 		
		- Fb sill penetration back		
		- Of single garage bay		
		- Fb top plate penetration in pantry		
		 Fb top plate penetrations at kitchen / bathroom wall 		
		- Add stud under triple 2x10s in kitchen		
		- Nail all exterior corners to code		
		- Provide 800 lb straps per plan (I believe this should be an CSPF with nail		
		pattern on sheeting) at dining room		
		 Solid block and nail off sheeting at breaks, front entry wall 		
		 Missing stud at owner suite/ gathering 		
		- Support rafter and end of top plate and tie into return wall above landing of		
		stairs by entry		
		- Nail off collar ties bedroom 4		
		- Provide collar ties throughout		
		- Tighten anchor bolts basement		

- Address header joist for plumbing near electrical panel nail to code or use hangers

- No Ufer bonding clamp

Comments: