

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20225048
Address: 1029 SW REDBUCK CIR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Tuesday, April 11, 2023

Corrective Action Required:

- | | | |
|---|--------------------------|--|
| 1 | Miscellaneous Correction | <ul style="list-style-type: none">- Missing anchor bolt garage at laundry- Fb penetration sill plate owner entry- Provide roof boot at radon vent- Provide 4 stud pack under I-beam at kitchen wall- Protect DWV at top plate kitchen by refrigerator- Missing sliding door- Security blocking 3 stud bays out for sliding door and front door- Complete gas line to fireplace- Seal gap to outside behind fireplace- Fb penetration sill under double LVL near door- Nail off exterior corner master suite- Complete plumbing to master tub- Fire block top of havc chase from joist space, off walk in closet- Double LVL at main floor stairs support to be structural 4x4- Missing window in media room- Provide collar ties at media room- Pan off or wrap outlets in plenum space upstairs |
|---|--------------------------|--|

Comments:

