## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20222969

Address: 2067 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, April 14, 2023

Residential

Corrective Action Required:

1 Misc

- -address holes drilled too close together and with two inches of edge of joist( partially fixed. New holes drilled do not meet code and some holes not addressed)
- -protect nm within 6 ft of attic access
- -missing nails in hanger and hanger 1st floor hall -provide stud pack at triple LVL at stair well wall
- -uncover covered deck and entry ceiling
- -uncover PFH exterior-maintain erosion control
- -address great room CSPF nailing not to code

**Comments:**