



May 5, 2023

Kevin Higdon Construction
Attn: Doug Slotter
PO Box 847
Lee's Summit, MO 64063

RE: 790 NE Algonquin St., Lee's Summit, MO 64064

Mr. Slotter,

At your request I have reviewed the repaired condition of the truss identified in the recent rough-in inspection summary dated April 10, 2023 specifically relating to the following comment:

- "Engineer to address repair of damaged truss above kitchen **Fasten OSB sheathing per engineer letter. Fasten to all truss members. 2 rows of nails for 2x3 and 3 rows of nails for 2x4"
 - *This truss has been repaired per the Engineer's recommendation as outlined in his letter dated June 8, 2022.*

Should you have any questions please do not hesitate to contact me.

Sincerely,

Kurt Krasick, PE
MAR Building Solutions

1445 SE Broadway | Lee's Summit, MO 64081

Office: 816.272.5435 | Cell: 816.803.3737

kurt@marbuildingsolutions.com | www.marbuildingsolutions.com

