#### CITY OF LEE'S SUMMIT

# Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

### **Inspection Summary**

Permit #: PRRES20215798

Address: 1609 SW 27TH ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Wednesday, May 10,

Residential 2023

#### Corrective Action Required:

1 Misc -identify hash lines appearing to be lib bracing on plans

- -secure all vertical dwv 2" in diameter or less see laundry
- -connect and secure gas line at fireplace (gas line not completed)
- -roof supports not to plans (no plans on site to check) roof supports landing on
- fire place/ entry wall.
- -missing nails in hangers above master
- -missing nails in stud shoes at master bath for dwv -address header size in master bath not to plans
- master batti not to plans
- -provide engineering floor joist city stamped plans on site and uploaded (not
- uploaded or stamped)
- -incorrect hanger for IvI above bed 4, missing nails in hanger above bed 4
- -address lvl's drilled through above bed 4 per 502.8.2
- -fire blocking must be of approved materials (see vertical to horizontal and top of furred out walls)
- -address I joist above basement bed bath sinks for cut drain above
- -fireblock above basement patio door(not approved material)
- -fireblock furr out wall into furr down in craft room
- -provide support for furr down in family room to floor joists above
- -cspf exterior nailing not correct
- -proper hold downs for cspf in mater bed where cantilever prohibits proper ...

nailing

**Comments:**