CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20220917

Address: 3533 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Failed Tuesday, June 06, 2023

Residential

Corrective Action Required:

1 Miscellaneous

Correction - Dishwasher does not have a water hammer device installed

- Dishwasher is not GFCI protected
- Kitchen backsplash plate cover is not secured
- Washer does not have a water hammer device installedSelf closing garage door hinge needs to be adjusted
- Interior above garage overhead door vertical board needs to be sealed at $% \left(1\right) =\left(1\right) \left(1\right) +\left(1\right) \left(1\right) \left(1\right) +\left(1\right) \left(1$

the ceiling

- Hot water tank whip needs to be secured better
- Exterior gas line needs to be sealed
- A/C whip needs to be attached to the exterior wall
- Sump pump discharge needs to be sealed at the siding

Comments: