



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	LUMBER LIQUIDATORS		
ADDRESS	300 NE M 291 HWY, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	GENESIS CONSTRUCTION MANAGEMENT LLC:	TELEPHONE	(816) 326-8157
ADDRESS	6116 N MERSINGTON AVE		
	GLADSTONE, MO 64119		
	Primary: (816) 326-8157		
	Cell: (816) 520-2233	RANDY @ 810-623-3667	

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2. IN FDM	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: M	Map#: 195H	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20110993

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection

1st Inspection 6/20/11

2nd Inspection

3rd Inspection

4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Monday, June 20, 2011
Corrective Action Required:			
1 (1)numerically address all front doors going into the business "300" 4" minimum numbers contrasting color			
(2) numerically address roll-up door with suite address "300" 4" minimum contrasting color			
(3) label the rear double doors that are not useable "THIS DOOR BLOCKED"			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
June 20, 2011	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	