

Kansas City, MO 64111 www.bdc-engrs.com

President

**PRINCIPALS** 

Christopher A. Beverlin, P.E.

Clark A. Basinger, P.E.

Clark A. Basinger, P.E. Michael J. Falbe, P.E. Richard C. Crabtree, P.E. Wayne E. Davis, P.E. Jeffrey L. Wright, P.E. Christopher W. Boos, P.E. Brandon M. Ford, P.E. Steven J. Brooks, P.E. Ryan M. Hagedorn, P.E.

> Administrative Manager James M. Spena

July 12, 2023

Isaac Leon Centric 520 W. Pennway St., Suite 100 Kansas City, MO 64108

RE: K1 Speed

Dear Isaac,

It is our understanding the city official did not inspect the K1 Light pole base but the 3<sup>rd</sup> party inspector, CFS Engineers, did. Attached is their report which shows the rebar and excavation is in compliance with the project documents.

We find this to be acceptable.

Sincerely,

**BOB D. CAMPBELL & CO., INC.** 

Structural Engineers

Clark Basinger, P.E.

СВ

cc: File/SLAGG2206





KCK Office 1100 W Cambridge Circle Dr., Suite 700 Kansas City, KS 66103 Phone: 913-627-9040

## Reinforcing Steel Inspection Report

Report #: 0006-000002-00

Client: Project:

D4 Holding, LLC

10624 S Eastern Ave, Suite A-975
Henderson, NV 89052-2982

Project:

22-1179
K1 Speed Lees Summit (Insp/Testing)
2911 NE Independence Ave

Lees Summit, MO

Activity Date: 05/17/2023 Technician: Burnett, Ken

Weather: Sunny Temperature (F): 81

Time On Site: 14:00 Time Off Site: 16:00 Total Time Including Travel (hrs): 3.00

## REINFORCING STEEL OBSERVATIONS

**DISCREPANCY: No** 

Location: Building - Light Post Pedestal

Location Details: Light pole bases on west side of building

Size and Spacing: Complies

Lap Slices: Complies Cleanliness: Complies Steel Grade: Complies

Clearance: Complies Corner Bar Placement: N/A Wall / Slab Dowel Placement: N/A

Embed Placement: N/A

Comments:

Reviewed By: Welhoff, Tracy