

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20100137, Building Permit - Commercial Address: 1255 NE DOUGLAS ST, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough John Borns Partial Thursday, June 23, 2011

Inspection - Commercial

Corrective Action Required

1 MISC SILL PLATE ANCHOR BOLTS MUST BE CENTERED IN PLATE; MIN

TWO BOLTS PER PLATE SECTION; ONE WITHIN 12" OF ENDS OF EACH PLATE SECTION; 4` MAX SPACING BETWEEN BOLTS;

WASHER + NUT WRENCH-TIGHTENED

Corrective Action Required

2 MISC IPC 305.

IPC 305.8: INSTALL SHIELD PLATES AT STUDS AND T&B PLATES WHEREVER SURFACE OF PIPE IS LESS THAN 1-1/2" FROM FACE OF FRAMING. SHIELD PLATES SHALL COVER THE AREA OF THE PIPE WHERE THE MEMBER IS NOTCHED OR BORED AND SHALL EXTEND A MINIMUM OF 2" ABOVE SOLE PLATES & BELOW TOP

PLATES. CHECK ALL.

Corrective Action Required

3 MISC

OK TO COVER WHEN READY FOLLOWING SURFACES: GWB

CEILING AT 104/105 BAR AREA;

Corrective Action Required

4 MISC

INSTALL STUD SHOE AND REINFORCE STUD AS DISCUSSED AT

WAITRESS STAION 106

Gas Piping John Borns Passed Thursday, June 23, 2011

Inspection -Commercial

Gas Service John Borns Passed Thursday, June 23, 2011 Inspection -Commercial **Sewer Service** John Borns Partial Thursday, June 23, 2011 Inspection -Commercial **Partial Correction** OK TO COVER WHEN READY 4" PVC SANITARY SEWER SERVICE MISC LINE FOLLOWING SEGMENTS: FROM GREASE INTERCEPTOR 120' SOUTH / SOUTHWEST / WEST; CONTINUED 30' WEST & DROPPED BELOW INTERSECTING STORM SEWER ELEVATION; EXTENDED TO WITHIN 2' OF CONNECTION @ MAIN, WHICH IS SUBJECT TO APPROVAL BY PUBLIC WORKS DEPT

Sewer Service Inspection -Commercial John Borns Passed

Thursday, June 23, 2011

Comments: GAS SERVICE WILL BE RELEASED.