

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20221047

Address: 795 NE ALGONQUIN ST, LEES SUMMIT, MO 64064
797 NE ALGONQUIN ST, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Kyle Beard	Failed	Wednesday, August 09, 2023

Corrective Action Required:

1	Misc	-Cover all excessive gaps between FlameBlock sheathings above units 795&797
---	------	---

Corrective Action Required:

2	Miscellaneous Correction	795 -roof sheathing above master bedroom has a hole that needs to be addressed 797 - rated assembly needs to be fire blocked vertically every 10 feet on center - one piece of roof sheathing has been installed and is not fire rated above the entry bathroom
---	--------------------------	---

Comments: