## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20231016

Address: 2075 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Shawn Hoffman Failed Wednesday,

Residential September 06, 2023

Corrective Action Required:

1 Misc -Complete nailing exterior nailing pattern at studs and header at single car PFH

-Clarify braced wall design at east side of single car bay-No portal frame design

present, panel is roughly 16"

-Have engineer address rafters landing on blocks and not connected to ceiling

joists (straps to be 32" OC)

-Midpoint dwv straps must prevent the pipes from moving perpendicular to

their axis

-Nail overlapping joists per code

-Seal fireblocking at fur out wall in master bath

-Provide Simpson LTTP2 straps At deck per plan

-Provide (2) nchor bolts at front basement bed plate break in middle 3rd of

plate

-Support end joists at deck

-Provide (2) 1/2" through bolts at post to beam connection

## Comments: