

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20231716

Address: 2012 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822014 SW HOLDBROOKS DR, LEES SUMMIT,
MO 640822016 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822018 SW HOLDBROOKS
DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Kyle Beard	Failed	Wednesday, September 20, 2023

Corrective Action Required:

1	Miscellaneous Correction	2018 - seal all exposed plywood wood that is missing (chipped) in the white flame blocking material
		2016 - seal all exposed plywood wood that is missing (chipped) in the white flame blocking material
		2014 - seal all exposed plywood that is missing (chipped) in the white fire flame blocking material - address metal channel about five feet south of the east wall ridge
		2012 Rated assembly was still being sealed by a contractor and could not be fully inspected.

THIS IS NOT A COMPLETE LIST

Not ready
09/14/2023 KBEARD 9:45am

Corrective Action Required:

- | | | |
|---|-----------------------------|--|
| 2 | Miscellaneous
Correction | 2018
- seal all exposed plywood wood that is missing (chipped) in the white flame blocking material |
| | | 2016
- seal all exposed plywood wood that is missing (chipped) in the white flame blocking material |
| | | 2014
- seal all exposed plywood that is missing (chipped) in the white fire flame blocking material
- address metal channel about five feet south of the east wall ridge |
| | | 2012
Seal all exposed plywood that is missing (chipped) in the white fire flame blocking material |

Comments: