## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

## **Temporary** Certificate of Occupancy

| Permit #:        | PRRES20213592   |
|------------------|---|
| Address:         | 3722 SW WALSH DR, LEES SUMMIT, MO 640823724 SW WALSH DR, LEES |
|                  | SUMMIT, MO 640823726 SW WALSH DR, LEES SUMMIT, MO 640823720   |
|                  | SW WALSH DR, LEES SUMMIT, MO 64082                            |
| Inspected On:    | Tuesday, October 17, 2023                                     |
| Inspected By:    | Kyle Beard  |
| Expiration Date: | 11/16/2023 12:00:00 AM  |

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.** 

| Inspection:                                 | Inspector: | Outcome: | Date: |
|---|------------|----------|-------|
| Occupancy Inspection -<br>Codes Residential | Kyle Beard | Pending  |       |

Corrective Action Required:

- 3 Miscellaneous 3726 Correction
  - Handrail height on back porch exceeds 38 inches Basement closet under stairs needs a hatch installed Garage to house self closing hinge is not working as intended Seal all penetrations in garage ceiling Garage attic access hatch needs to be in place to check for proper seal Seal exterior penetrations of all units Permit is required on installed sprinkler systems on all units

Corrective Action Required:

4 Miscellaneous 3726 Correction

> Handrail height on back porch exceeds 38 inches Basement closet under stairs needs a hatch installed Garage to house self closing hinge is not working as intended Seal all penetrations in garage ceiling Seal exterior penetrations of all units Permit is required on installed sprinkler systems on all units

## Corrective Action Required:

5 Miscellaneous 3726

Correction -Ba

-Back porch handrail is still too high. Code is no more than 38 inches high from the tread nosing

-all units need to have exterior penetrations sealed

-3726 needs to have the exterior sump pump extension replaced (it's broken)

All units now have a TCO issued 10/16/2023 KBEARD