## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20220388Address:2034 SW HARVEST MOON LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspection - Residential	Mitchell Schwarz	Failed	Wednesday, October 25, 2023	
Corrective Action Required:				
1 Misc				
	-anchor bolts to be in the middle 1/3 of sill plate			
	-return air stud cavity shall not convey air from more than one floor(see dining room)			
	-seal return air space at	eal return air space at master bed entry and in master bedroom		
	-fireblock wall space to	ceiling space at maste	er bed E wall	
	-nail exterior wall studs together to code and plans			
	-lib on wall that has be	en headered off		
	-h2.5 missing on heade	r at bed 4		
	-osb used as blocking for	or rafters		

**Comments:**