CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20220350Address:2038 SW RED BARN LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Alex Fischer	Failed	Thursday, November 09, 2023	
Corre	ctive Action Required	:			
2	Misc	 Needs attic access i 	- Needs attic access in garage		
		-Need vent in same a	-Need vent in same area		
		-Secure NM in garage	-Secure NM in garage chase		
		-Fire stop garage cha	-Fire stop garage chase DWV		
		-Secure hip and valle	-Secure hip and valley in garage attic space		
		-Need 75 percent be	-Need 75 percent bearing at rafter at small garage door		
		-Welding certificate	-Welding certificate for garage beams		
		-Fire stop at laundry	-Fire stop at laundry top plate next to garage chase		
		-Need solid blocking	-Need solid blocking between laundry and breakfast area top plate at load		
		bearing wall	bearing wall		
		-Support cut joist ov	-Support cut joist over kitchen		
		-Protect NM at pantr	-Protect NM at pantry and mud room		
		-Solid fire block left	side of return air chase		
		-Block air return mas	ter bedroom		
		-Fire block upstairs r	eturn air chase		
		-Support valley and r	-Support valley and rafters at 2nd floor front bathroom		
		-Install lateral suppo	-Install lateral support at ends of ceiling at side bedroom		
		-Missing nails at han	-Missing nails at hanger at stairs to basement		
		-Address notched flo	-Address notched floor joist in basement at -DWV under master bathroom		
		-Secure DWV every 4			
		-Support DWV from			

Comments: