CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20232719

Address: 1534 SW ARBOR FALLS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Monday, November

Residential 20, 2023

Corrective Action Required:

1 Miscellaneous 1532 hawthorn

Correction

Third car garage is missing a 5/8 inch anchor bolt with a 3x3 plate and nut Double garage door sole plate has been over notched at anchor bolt

LIB in bedroom 2 is missing nails

Plumbing vent line at sole plate by refrigerator needs the BOCA moved to

cover past both lines horizontally

Truss tie down straps in great room by fireplace are all missing two nails at

the top

Water lines in the basement linen closet are not supported in the ceiling Top plate Fire blocking is needed in basement bedroom 3 above entry door

Secure gas line in basement at rec room going up to the great room

Front and back porch truss tie downs could not be verified because of soffit

already installed

Garage portal framing inspection could be be fully verified due to siding

Comments: