CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20234721 Address: 2002 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822004 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822006 SW HOLDBROOKS DR, LEES SUMMIT, MO 640822008 SW HOLDBROOKS DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Erosion Control		Kyle Beard	Failed	Wednesday, December 06, 2023	
Corrective	Action Required:				
1	Miscellaneous Correction	Some erosion control has been damaged or is missing. Full erosion control must be maintained until CofO			
Corrective	Corrective Action Required:				
2	Miscellaneous Correction	Some erosion control is missing or damaged. Required gravel is missing from the front of the lot. Street has mud and gravel in it creating a hazard for motorists and pedestrians. Gravel is needed, erosion barriers need to be installed and STREET NEEDS TO BE CLEARED. No inspections will be completed until full erosion control is in place and street maintenance is obtained. Have all items completed before a stop work order is issued			
		12/04/2023 KBEARD			
Corrective Action Required:					
3	Miscellaneous Correction	by the builder without pro erosion and sediment con pamphlet with the builder	ot in place at 9:15 am. An all oper erosion control. The str trol standards were not in p r about the control standard ed to be fixed before sched ection was denied.	reet was clean, but blace. I did leave a Is and handed it to him	

Full erosion control must be in place when scheduling inspections and maintained until CofO 12/06/23 KBEARD 9:20 am

Comments: