

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20235952
Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Kyle Beard	Failed	Monday, December 11, 2023

Corrective Action Required:

1 Miscellaneous
Correction

Corrective Action Required:

2 DCM2 ESC
DEFICIENT
INSTALLATION

DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
UNTIL ADEQUATE EROSION CONTROL PROVIDED.

Storm drain along the East side of property needs to be better protected
from sediment and silt fence is torn down. Silt fence is not installed around
dirt pile on south side of property to control runoff

12/11/23 KBEARD

Comments: