CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20232322

Address: 2133 SW RUTHERFORD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Friday, December 15,

Residential 2023

Corrective Action Required:

1 Miscellaneous 2133 sw Rutherford. All rough

Correction

Verify if trusses in garage have adequate support at joist hangers being

nailed to sheeting

Verify if truss tie down screws in garage are adequate length to penetrate

and secure through 3 depths of top plate

Fire block in garage at low voltage wire penetrations Strap in needs in the garage top plate at N/E corner Chase top in party needs to be fire blocked at the ceiling

Renail double joist hanger at stair landing

Strap is needed in top plate at stair landing in corner Attic access requires a minimum of 30 inches of head room

Nail N/E corner of bedroom one to code Strap corner of bedroom 1 closet top plate

Gas line is not bonded

Corrective Action Required:

2 Miscellaneous 2133 sw Rutherford. All rough 2nd inspection

Correction

-Verify (engineers letter) if trusses in garage have adequate support at joist

hangers being nailed to sheeting -garage attic space is not vented

Comments: