

December 22, 2023

via upload

Ms. Sharon Bloom City of Lee's Summit, Missouri 220 SE Green Street Lee's Summit, MO 64063

Re: Lee's Summit Downtown Market Plaza

Lee's Summit, MO 64063 Architect's Project 18225R21006

Dear Ms. Bloom:

In response to The City of Lee's Summit Missouri Permit Application Plan Review comments dated between November 14 and November 16, 2023, a copy of which is attached for reference, we offer the following responses:

#### Fire Plan Review:

Responses will be provided in Final Development Submittal.
Have adjusted Fire-Flow in Code Analysis. See Sheet G-101.
Updated FA system to voice messaging system.
Proposed address number location has been added to the front elevation. See Sheet A-201. Final approval to be provided by City of Lee's Summit.
Knox box relocated to 6 feet above finished floor (AFF) above the FDC.
Refer to Final Development Plan Response Letter.
Sprinkler Shop Drawings will be a deferred submittal.
Occupant load has been recalculated for both tables and chairs as well as non-fixed seating. See Sheet G-101.
Maximum Occupancy sign parameters have been added. See Sheet I-301.
Connected high-volume-low-speed (HVLS) fans to the fire alarm system. See Sheet FP-101. Updated fire alarm matrix. See Sheet FP-000.
Added building-mounted exterior lighting fixture Types L7 and L8 to emergency lighting inverter for all egress exits.
Fire extinguishers have been added in the Main Lobby and the east Restroom Corridor. See Sheet G-101.

#### **Building Plan Review:**

Response to Comment 1: Responses will be provided in Final Development submittal.

Response to Comment 2: City has a contract with Geotechnology LLC to perform special

instructions. City/Owner will provide letter to City/authority

having jurisdiction.

Response to Comment 3: Under review with the Health Department.

Response to Comment 4: Understood. Will make Contractor aware.

Response to Comment 5: Per Specification Section 077200, the guard will be mounted

to the curb of the roof hatch. Basis of Design for the roof hatch and guard have been added to the Roof Plan. See Sheet A-121.

Response to Comment 6: Per Specification Section 077200, the guard will be mounted

to the curb of the roof hatch. Basis of Design for the roof hatch and guard have been added to the Roof Plan. See Sheet A-121.

Response to Comment 7: Added 3-inch backflow preventer and associated domestic

water piping and accessories in Storage 111 as well as a 4-inch floor drain and associated waste and vent piping; refer to Sheet P-101 for updates. See Sheets P-301, P-302, and P-401 for updated water isometric, waste and vent isometric, and

Plumbing Fixture Schedules, respectively.

Response to Comment 8: Added building-mounted exterior lighting fixture Types L7

and L8 to emergency lighting inverter for all egress exits.

## **Licensed Contractors:**

Response to Comment 1: Understood. Subcontractors have not been selected at this

time.

We look forward to your approval.

Sincerely,

**GLMV** Architecture

Chaz Pruente, AIA Project Manager

RCP/as

**Enclosures** 

c (w/enc.): 18225R21006

# **Permit Application Status**

PRCOM20235733

In order to schedule inspections, you need to be signed in.

#### Summary-

Application Number: PRCOM20235733

Application Type: Building Permit - Commercial

Application Status: In Plan Review

Property Owner's Full Name: THE CITY OF LEES SUMMIT MISSOURI

Category of Work: NEW COMMERCIAL

Description of Work: NEW MULTI-FUNCTIONAL SPACE FOR FARMERS MARKET, GATHERING SPACE

FOR EVENTS, AND DAILY ACTIVITIES

Application Date: 11/01/2023 Expiration Date: 05/14/2024

#### Locations-

Locations: Address

220 SE GREEN ST, LEES SUMMIT, MO 64063

Address

205 SE GREEN ST, Unit:B, LEES SUMMIT, MO 64063

Property

61230151300000000

Property

61230151400000000

Property

61230162300000000

Address

203 SE GREEN ST, LEES SUMMIT, MO 64063

## Contacts

Property Owner: THE CITY OF LEES SUMMIT MISSOURI, Address:220 SE GREEN ST Email Contact: TYLER STOTLER, Address:MCCOWN GORDON, Phone:(816) 518-0622

Applicant: MCCOWN GORDON CONSTRUCTION LLC, Address:850 MAIN ST, Phone:(816)

960-1111

Contractor-Mechanical: Contractor-Electrical: Contractor-Plumbing:

Architect: GLMV ARCHITECTURE , Address:9229 WARD PKWY SUITE #210, Phone:(816)

444-4200

Special Inspections:

Property Owner: CITY OF LEES SUMMIT, Address:PO BOX 1600

#### Reviews

Review Type	Outcome	Est. Completion Date	Completed
Fire Plan Review	Rejected	11/15/2023	11/16/2023
Reviewer:	Jim Eden		
Corrections:	Correction 1:	Miscellaneous Correction	
	Status:	Corrective Action Required	
	Date Status Changed:	11/16/2023	
	Comments:	Address site issues listed on	the Final
		Development Plan.	
	Correction 2:	Miscellaneous Correction	

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: Code Analysis- Required Fire Flow-Local

Amendment only allows a 50% reduction in fire

flow for a fully sprinklered building.

Correction 3: Construction documents for fire alarm systems

Status: Corrective Action Required

Date Status Changed: 11/16/2023

2018 IFC 907.1.1- Construction documents.

Construction documents for fire alarm systems shall be submitted for review and approval prior to system installation. Construction documents shall include, but not be limited to, all of the following: 1. .A floor plan which indicates the use of all rooms. 2. Locations of alarm-initiating and notification appliances. 3. Alarm control and trouble signaling equipment. 4. Annunciation. 5. Power connection. 6. Battery calculations. 7. Conductor type and sizes. 8. Voltage drop calculations. 9. Manufacturers, model numbers and listing information for equipment, devices and materials. 10. Details of ceiling height and construction. 11. The interface of fire safety control functions. Action required- Provide shop drawings for review and approval. A voice messaging system may be required.

Correction 4: Address numbers required

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: 2018 IFC 505.1- Address numbers. New and

existing buildings shall have approved address numbers, building numbers or approved building identification placed in a position that is plainly legible and visible from the street or road fronting the property. These numbers shall contrast with their background. In Multi-tenant commercial building where tenants have multiple entrances located on different sides of the building, each door shall be addressed. Address numbers shall be Arabic numerals or alphabet letters. Numbers shall be a minimum of 4 inches (102 mm) high with a minimum stroke width of 0.5 inch (12.7 mm).

Correction 5: Knox box required

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments:

2018 IFC 506.1- Where required. Where access to or within a structure or an area is restricted because of secured openings or where immediate access is necessary for life-saving or

fire-fighting purposes, the fire code official is authorized to require a key box to be installed in an approved location. The key box shall be of an approved type and shall contain keys to gain necessary access as required by the fire code official. Action required- Provide a Knox box 6'AFF over the FDC. Order at Knoxbox.com.

Correction 6: Locks on gates or barriers

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: 2018 IFC 506.1.1-Locks. An approved lock shall he installed on gates or similar harriers when

DO INDICATOR OF GREEN OF STITLE PARTIES WITHOUT

required by the fire code official. Action required-Provide Knox padlocks, or key switch if electric gate, for the gates on the fire lane east of the

market.

<u>Correction 7:</u> Construction documents - Fire protection systems

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: 2018 IFC 901.2- Construction documents. The

fire code official shall have the authority to require construction documents and calculations for all fire protection systems and to require permits be issued for the installation, rehabilitation or modification of any fire protection system. Construction documents for fire protection systems shall be submitted for review and approval prior to system installation. Action required- Provide sprinkler shop drawings for

review and approval.

Correction 8: Miscellaneous Correction

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: Code Analysis- Recalculate the occupant load for

the total square footage of the space based on Net and Gross Floor Area as defined by the IFC and IBC Commentary. Provide occupant loads and signage for the most likely use of the space for tables and chairs(15sqft/person), non-fixed

seating (7sqft/person) and mercantile

(60sqft/person).

Correction 9: Miscellaneous Correction

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: The HVLS fans shall be connected to the fire

alarm system. Verified on alarm plans and at

inspection.

Correction 10: Emergency power for illumination

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: 2018 IFC 1008.3.1 & 3.2 Emergency power for

illumination. The power supply for means of egress illumination shall normally be provided by the premises' electrical supply. In the event of power supply failure, an emergency electrical system shall automatically illuminate all of the following: 1. Aisles and unenclosed egress stairways in rooms and spaces that require two or mor means of egress. 2. Corridors, interior exit stairways and ramps and exit passageways in buildings required to have two or more exits. 3. Exterior egress components at other than their levels of exit discharge until exit discharge is accomplished for buildings required to have two or more exits. Action required- Provide exit

discharge emergency lighting.

Portable fire extinguishers - conspicuous Correction 11:

locations

Status: Corrective Action Required

Date Status Changed: 11/16/2023

Comments: 2018 IFC 906.5- Conspicuous location. Portable

fire extinguishers shall be located in conspicuous locations where they will be readily accessible

Reviewer Comments:		and immediately available for locations shall be along norm unless the fire code official dhazard posed indicates the raway from normal paths of the Provide fire extinguishers in east restroom corridor. This the market area is closed, but open for outdoor events.	r use. These nal paths of travel, etermines that the need for placement ravel. Action required- the main lobby and will allow acces when
	D : 4 1	44/45/0000	44/45/0000
Building Plan Review	Rejected	11/15/2023	11/15/2023
Reviewer:	Joe Frogge		
Corrections:		Final Development Plan	
	<u>Status:</u> <u>Date Status Changed:</u>	Corrective Action Required 11/14/2023	
	Comments:	The building permit for this p issued until the Developmen Department has received, ap processed the Final Develop required: Comment is inform	t Services oproved, and oment Plan. Action
	Correction 2:	IBC 1704.2 Special Inspection	ons
	Status:	Corrective Action Required	
	<u>Date Status Changed:</u>	11/14/2023	
	Comments:	2018 IBC 1704.2 Special ins application is made for const in this section, the owner or professional in responsible commer's agent shall employ approved agencies to perfor construction on the types of Section 1705. These inspect the inspections identified in LOrdinances Chapter 7. (see exceptions) Action required: special inspections / letter of company contracted to performspections.	truction as described the registered design charge acting as the one or more minspections during work listed under ions are in addition to Lee's Summit Code of code section for Provide statement of the responsibility from
	Correction 3:	Health Dept Review	
	Status:	Corrective Action Required	
	Date Status Changed:	11/14/2023	
	Comments:	For the Health Department of Sees with the Jackson Coun Department, Environmental (816) 797-7162. Health Department of the City of Lee's required: Comment is information.	ty Public Works Services Division, at artment approval is ny type of building Summit. Action
	Correction 4:	Health Dept Inspection	
	Status:	Corrective Action Required	
	Date Status Changed:	11/14/2023	
	Comments:	For the Health Department in Deb Sees with the Jackson of Department, Environmental (816) 797-7162. Health Department prior to receiving an from the City of Lee's Summ Comment is informational.	County Public Works Health Division at artment approval is ny type of Occupancy
	Correction 5:	IMC 306.5 Equipment on roo	ofs
	Status:	Corrective Action Required	
	Date Status Changed:	11/14/2023	

Comments: 2018 IMC 306.5 Equipment and appliances on roofs or elevated structures. Where equipment requiring access or appliances are located on an elevated structure or the roof of a building such that personnel will have to climb higher than 16 feet above grade to access such equipment or appliances, an interior or exterior means of access shall be provided. Such access shall not require climbing over obstructions greater than 30 inches in height or walking on roofs having a slope greater than 4 units vertical in 12 units horizontal. Such access shall not require the use of portable ladders. Where access involves climbing over parapet walls, the height shall be measured to the top of the parapet wall. Permanent ladders installed to provide the required access shall comply with the following minimum design criteria: 1. The side railing shall extend above the parapet or roof edge not less than 30" (see code section for additional construction requirements) Action required: Provide side rail extension at roof hatch.

Correction 6: IBC 1015.7 Roof access - roof hatch guard

Corrective Action Required

Status: Date Status Changed: 11/14/2023

Comments: 2018 IBC 1015.7 Roof access. Guards shall be provided where the roof hatch opening is located within 10 feet of a roof edge or open side of a walking surface and such edge or open side is located more than 30 inches above the floor, roof or grade below. The guard shall be constructed so as to prevent the passage of a sphere 21 inches in diameter. (see code for exception) Action required: Comment is informational. If mechanical screen is to act as fall protection guard it must meet strength/loading requirements in IBC 1607.8.

Correction 7: IPC 608.1 Backflow

Status: Corrective Action Required

Date Status Changed: 11/15/2023

Comments: 2018 IPC 608.1 General. A potable water supply

system shall be designed, installed and maintained in such a manner so as to prevent contamination from nonpotable liquids, solids or gases being introduced into the potable water supply through cross-connections or any other piping connections to the system. Backflow preventer applications shall conform to Table 608.1, except as specifically stated in Sections 608.2 through 608.17.10. 2018 IPC 604.8 Water Pressure reducing valve or regulator. Where water pressure within a building exceeds 80 psi static, an approved water-pressure reducing valve conforming to ASSE 1003 or CSA B356 with strainer shall be installed to reduce the pressure in the building water distribution piping to not greater than 80 psi static. Action required: At water service entry provide shut-off valve, RPZ backflow preventer (inside building), and pressure reducing valve.

Correction 8:

IBC 1008.3 Emergency power for illumination - at

exit discharge

Status: Corrective Action Required

Date Status Changed: 11/15/2023

Reviewer Comments:	<u>Comments:</u>	2018 IBC 1008.3 Emergency illumination. The power supplegress illumination shall norrethe premises' electrical supplements of power supply spaces that require two or man emergency electrical systautomatically illuminate all of 1. Aisles. 2. Corridors. 3. Exitand ramps. 1008.3.2 Building power supply failure in building or more means of egress, an electrical system shall autom of the following areas: 1. Intestairways and ramps. 2. Intestairways and ramps. 3. Exit Vestibules and areas on the used for exit discharge in acc Section 1028.1. 5. Exterior laby Section 1010.1.6 for exit directly to the exit discharge. and Spaces. In the event of an emergency electrical systautomatically illuminate all of 1. Electrical equipment room centers. 3. Fire pump rooms. 5. Public restrooms with an asquare feet. Action required: lighting at exterior landing of	ly for means of mally be provided by ly. 1008.3.1 General. failure in rooms and ore means of egress, em shall the following areas: the
Licensed Contractors	Rejected	11/15/2023	11/14/2023
Reviewer:	Joe Frogge		
Corrections:	Correction 1:	LC - MEP Subs	
	Status:	Corrective Action Required	
	Date Status Changed:	11/14/2023	
	Comments:	Lee's Summit Code of Ordina - Business License. (excerpt than a licensed contractor or licensed contractor, shall engolumbing or mechanical busi installation or maintenance u in accordance with this section MEP subcontractors are requipermit. Provide company nar contractors.	) No person, other employees of a gage in electrical, ness, construction, inless duly licensed on. Action required: uired to be listed on
Reviewer Comments:			
Final Development Plan Review	Pending	11/15/2023	
Reviewer:	Dawn Bell		
Reviewer Comments:			
Alarm Plan Review	Pending		
Reviewer:	Jim Eden		
Reviewer Comments:			
Sprinkler Plan Review	Pending		
Reviewer:	Jim Eden		
Reviewer Comments:			
Health Department Review	Pending		
Reviewer:	Joe Frogge		
Reviewer Comments:			
- Fees	I.		

Paid Fees	Amount	Paid	Owing	Date Paid
None	\$0.00	\$0.00	\$0.00	
Outstanding Fees	Amount	Paid	Owing	Date Paid
Totals:	\$0.00	\$0.00	\$0.00	

Total Amount Payable Online: \$0.00

# - Inspections-

There are no inspections for this permit application.

# Documents & Images—

Date Uploaded	File Type	Document Name
11/01/2023	Application Form	2019_Commercial Permit Application
11/01/2023	Engineer Report/Study	23-10-31_LSDM_SWPPP
11/01/2023	Plans	COMBINED DRAWING SET - VOL 1
11/01/2023	Plans	COMBINED DRAWING SET - VOL 2
11/01/2023	Specifications	<u>Specifications</u>
11/02/2023	Engineer Report/Study	23-23 LS Market Plaza - Calculations
11/02/2023	Letter	License Tax Bill
11/16/2023	Letter	DS P/R Corrections Document