CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20234774

Address: 3734 SW MARYVILLE PL, LEES SUMMIT, MO 640823736 SW MARYVILLE PL, LEES SUMMIT, MO

640823738 SW MARYVILLE PL, LEES SUMMIT, MO 640823740 SW MARYVILLE PL, LEES

SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Kyle Beard Failed Friday, January 26,

2024

Corrective Action Required:

1 Miscellaneous Some erosion control is missing, torn down or not installed. Full erosion

Correction control must be maintained until CofO.

Corrective Action Required:

2 Miscellaneous Full property erosion control is still missing. Gravel is now spreading through

Correction the street. Immediate attention is needed. Street needs to be swept. Full

erosion control is required until CofO.

Corrective Action Required:

3 Miscellaneous Full erosion control is missing or damaged and is not effective. Streets have Correction mud and gravel in the street and needs immediate attention so harm does

mud and gravel in the street and needs immediate attention so harm does not occur to pedestrians. Clean streets immediately before stop work order

is issued.

01/26/2024 K.Beard 11:30am

Comments: