

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOMCOM20230057

Address: 451 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081443 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081445 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081447 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081449 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081453 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081441 SW LONGVIEW BLVD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Shawn Hoffman	Failed	Friday, February 02, 2024

Corrective Action Required:

1	Misc	DO NOT SHEET ROCK
---	------	-------------------

Will Check at occupy :
All front stoops 32" code is 36"
Tempered windows
Garage landing

441

- OK to insulate

2/2

- Boca plates first floor sill plate

- Fire block mechanical chase to prevent flame into joist space

- Protect stair stringers at garage above mechanical room

443

• OK to insulate

2/2

- window at second floor stairs landing to be Tempered
- Fire block top of mechanical chase at second floor

445

- OK to insulate

2/2

- landing for garage stairs under 36"
- Protect stair stringers at garage above mechanical room

447

2/2

- window at bottom of stairs second floor to be Tempered
- Fire caulk penetration above third floor back toilet in attic space

- 449

2/2

- window at second floor stairs landing to be Tempered

- 451

- Missing rock wool third floor demising wall top plate back bathroom closet

2/2

- window at second floor stairs landing to be Tempered

- 453

2/2

- protect stair stringers above mechanical room garage

DI NOT SHEET ROCK

Comments: