CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20235952

Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Kyle Beard Failed Monday, February 05,

2024

Informational:

2

1 Miscellaneous Erosion control is in place at the time of sewer inspection. Full erosion

Correction control must be maintained until full CofO

Partial Correction:

Miscellaneous Erosion control is damaged and not effective at the front of the lot. Dirt and Correction

gravel is in the street. Clean street and repair or replace damaged erosion

measures. Full erosion control must be maintained until CofO.

01/29/24 KBEARD

Partial Correction:

3 Miscellaneous Erosion control is damaged and not effective at the front of the lot. Dirt and Correction

gravel is in the street. Clean street and repair or replace damaged erosion measures. Erosion control is needed across the street where the plumbers

left a mound of dirt.

As Ethan and I discussed verbally at a earlier date, the storm drain in the

backyard needs full erosion control so mud and debris does not enter it

Have full erosion control in place before scheduling any inspections. No inspections will be conducted until full erosion control is completed

01/31/24 K.Beard

Corrective Action Required:

Full erosion control includes LOT ACCESS under Lee's Summit erosion Miscellaneous

| Correction | &sediment control standards. Have lot access addressed before scheduling |
|------------|--|
| | any inspections |

Comments: