CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRCOM20231204Address:2951 SE SHENANDOAH PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
Erosion Control		Khanh Nguyen	Partial	Thursday, January 11, 2024	
Informati	onal:				
1	Misc	around the construction a around existing silt fence,	-23 BR Erosion control needs to be fix. Silt fences need to be added und the construction area as well as debris and brush need to be removed und existing silt fence, so silt fence is visible. Need to add more rock in crances to help control less dirt getting on the roadway.		
10-5-2		8-22-23 BR Erosion control is up and working order.			
			-5-23 BR Erosion control fence need to be repaired. There are several cations on the fence that needs to repair to brakes in the fence line.		
			ol fence need to be repaired t needs to repair to brakes		
		contractor this morning ab informed me that they wa	ol fence need to be repaired bout getting fence repaired. Is getting the fence repaired ot repaired which needs to	. Which the contractor d at noon today. It's 4:00	
		10-24-23 BR Erosion contro	ol is not to LS Specifications	site is shut down.	

10-24-23 BR Contractor brought erosion control up to compliance with LS specification.

10-31-23 BR Erosion control is up and working order

11-13-23 BR Erosion control needs to be fix. There are several locations on the fence line that need to be repaired.

11-15-23 BR Erosion control is up and working order.

11-30-23 BR Erosion control is up and working order

12-12-23 BR Erosion control is up and working order

12-18-23 BR Erosion control is up and working order

12-28-23 BR Erosion control is up and working order

1-4-24 BR Erosion control is up and working order

1-11-24 BR Erosion control is up and working order

1-25-24 BR Erosion control is up and working

2-2-24 BR Erosion control is up and working order

Comments: