## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20233614Address:2136 SW OSAGE DR, LEES SUMMIT, MO 640822134 SW OSAGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Kyle Beard	Failed	Tuesday, February 06, 2024
Informational: 1 Miscellaneous Correction Corrective Action Required:		Portal inspections passed		
2	Miscellaneous 2134 SW Osage all rough Correction			
	Chase between garage and bedroom 2 needs to be fire blocked at the ceiling			
	GT stud pack in garage and bedroom 1 is missing Gang plate in pantry truss is damaged Joist hangers missing in bedroom 2 ceiling Upper stair case does not bear 1 1/2 inches on sup Blocking is missing in one space above the suppor Roof boots are not installed		is damaged edroom 2 ceiling bear 1 1/2 inches on suppor space above the support Ib	•
GT stud pack missing GT stud pack is missi Upper stair case doe Plywood decking is v		Ceiling joist hangers are n GT stud pack missing in ga GT stud pack is missing on Upper stair case does not Plywood decking is within	rage to bedroom 2 e stud in bedroom 1 bear 1 1/2 inches on suppor	

units

**Comments:**