CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20234908

Address: 2143 SW HOOK FARM DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Thursday, March 14,

Residential 2024

Corrective Action Required:

1 Misc Garage portal frame inspection only

-nailing incomplete and spacing incorrect

Corrective Action Required:

2 Misc

- -garage portal frame did not pass previous inspection see above note
- -anchor bolts to be in the middle 1/3 of sill plate (garage and basement)
- -3 studs required at exterior wall corners see SE garage wall
- -fire block top plate penetrations in garage S wall
- -address cut ceiling joist above pantry
- -address ceiling joists running wrong direction above garage entry area, pantry, laundry
- -windows in dining room will need to be tempered at occupancy stage
- -address over span header above master bedroom window
- -address 3/4 osb used as shim under roof supports for bed 2
- -address notched floor joists above bed 4 for shower above
- -provide support for furr down ceiling joists to floor joist above
- -exterior wall corners at basement 3 studs required (wall corners not tied together)
- -all 2x6 walls shall have double king studs at door and window openings per plans

Comments: