

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20235952
Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Wednesday, March 20, 2024

Corrective Action Required:

2	Miscellaneous Correction	1932 SW Merryman. All rough. (2) Garage north wall top plate has a break less than two feet from the corner Fire block basement north wall vertically every 10 feet on center Fire block basement walls every 10 feet vertically on center (floor to ceiling) Loose fitting insulation is not considered fire blocking Air vent in bedroom 4 is not fully cut open (will not allow proper air flow) Back porch deck support column needs 2 all through bolts installed (lag bolts are not all through bolts) New wire ran in kitchen to patio at top plate needs to be fire blocked
---	--------------------------	--

Comments: