

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20235952  
Address: 1932 SW MERRYMAN DR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Kyle Beard	Failed	Monday, March 25, 2024

Corrective Action Required:

2	Miscellaneous Correction	1932 SW Merryman. All rough. (3)  -Garage north wall top plate has a break less than two feet from the corner (strap was installed on the wrong top plate) -Fire block basement walls every 10 feet vertically on center (floor to ceiling) Loose fitting insulation is not considered fire blocking R392.11.1#7 Back porch deck support column needs 2 all through bolts installed (lag bolts are not all through bolts)
---	--------------------------	--

**Comments:**