# CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

### **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20231105

Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -Robb Popp Failed Monday, April 08, 2024

Commercial

Informational:

1 Misc -Building 1, Segment A, 1st through 4th Floor for first layer of rated assembly

behind all tubs approved

Corrective Action Required:

2 FIRST FLOOR

Corrective Action Required:

SECOND FLOOR Corrective Action Required:

THIRD FLOOR \*BUILDING A:

\*\*\*\*\*\*\*\*UNITS AND CORRIDOR ONLY

- -THROUGHOUT
- -Address over spanned dryer ducts per manufacturer's listing
- -Fire caulk all dryer ducts through exterior walls-
- -Install kickers at trusses per structural plans S3.12-INSTALL AT MAX 48" OC

301-strap over bored top plate

304-Seal draft stop, over bored stud

305-strap over bored top plate

306-3 nm cables in single top plate penetration 307-strap top plate at closet lapped less than 48"

308-3 nm cables in single top plate penetration, missing stud at back room,

address hole in truss top chord

#### Corrective Action Required:

5 FOURTH FLOOR

\*BUILDING A:

\*\*\*\*\*UNITS AND CORRIDOR ONLY

\*\*THROUGHOUT:

-Decks not ready for inspection

-Address over spanned dryer ducts per manufacturer's listing

-OK FOR RC EXCEPT AS NOTED

412

-Fire caulk dryer duct through exterior wall

#### **Comments:**