

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20236296

Address: 2124 SW HOLDBROOKS DR, LEES SUMMIT, MO 64082  
2122 SW HOLDBROOKS DR, LEES SUMMIT,  
MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control</b>	Dustin Agcopra	Passed	Tuesday, April 23, 2024

Informational:

1	Miscellaneous Correction	Erosion control is in place at the time of sewer inspection. Full erosion control must be maintained until full CoFO.
---	-----------------------------	---

Informational:

2	Miscellaneous Correction	Full erosion control is in place and needs to be maintained until Cofo
---	-----------------------------	--

Informational:

3	Miscellaneous Correction	Full erosion control is in place and must be maintained until full Cofo
---	-----------------------------	---

Informational:

4	Miscellaneous Correction	Full erosion control is in place and must be maintained until full Cofo
---	-----------------------------	---

Informational:

5	Miscellaneous Correction	Full erosion control is in place and must be maintained until full Cofo
---	-----------------------------	---

Corrective Action Required:

6	Miscellaneous Correction	Erosion control at the street is torn, blown down or damaged and no longer serves its intended purpose. Full erosion control must be maintained until Cofo
---	-----------------------------	--

Corrective Action Required:

7	DCM3 ESC REQUIRED 2 DAY	4-17-24 Dustin A. EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE WITHIN TWO BUSINESS DAYS.
---	----------------------------	--

Corrective Action Required:

8	DCM1 ESC	EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE
	REQUIRED NO	PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.
	FURTHER INSP	4-19-24 Dustin A, Still no erosion control in place

**Comments:**