

Professional advice should be sought regarding handling, installation, temporary and permanent bracing before erecting trusses. Temporary and permanent bracing is required during installation of trusses to prevent possible collapse.

For general guidance regarding bracing, consult "BCSI-06" available jointly from WTCA & TPI.

Premier Building Supply must be notified of any issues requiring a back charge prior to any work being done. Premier Building Supply reserves the right to use it's service staff in lieu of being back charged.

ROOF AREA: 2,219 GABLE AREA: 555 HORIZONTAL OVERHANGS: 116 HIP LINES: 0 RAKED OVERHANGS: 181		
GABLE AREA: 555 HORIZONTAL OVERHANGS: 116 HIP LINES: 0 RAKED OVERHANGS: 181	TRUSS QUANTITY: 57	
HORIZONTAL OVERHANGS: 116 HIP LINES: 0 RAKED OVERHANGS: 181	ROOF AREA: 2,219	
HIP LINES: 0 RAKED OVERHANGS: 181		
RAKED OVERHANGS: 181	HORIZONTAL OVERHANGS:	116
	HIP LINES: 0	
	RAKED OVERHANGS: 181	
RIDGE LINES: //	RIDGE LINES: 77	
VALLEY LINES: 55	VALLEY LINES: 55	

- EL EXTREMO IZQUIERDO DE LOS TRUSSES (VEA LOS PERFILES)

