## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20236557 Address: 3723 SW CLAYTON PL, LEES SUMMIT, MO 640823725 SW CLAYTON PL, LEES SUMMIT, MO 640823727 SW CLAYTON PL, LEES SUMMIT, MO 640823721 SW CLAYTON PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Kyle Beard	Failed	Thursday, May 02, 2024	
Corrective	Action Required:				
3	Miscellaneous Correction	3721-3727 All rough			
		3721			
		joist for extra support. weight support)	2x10 porch joist for plumbing waste line has been over bored( add new 2x10 oist for extra support. The upstairs toilet sits on just plywood and needs weight support) 2 continuous 2x10 headers are not installed at windows in bedroom 1 (have		
		engineer address)			
		Fire block top of chases in bedroom 1 shower (fire block 1/4 inch gaps) HVAC in bathroom 2 in falling down			
		3723-3725&3727 all pas	sed all rough		
		DO NOT INSULATE util a	all rough and rated as	sembly all pass. KBEARD	

Comments: