

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20113001, Building Permit - Commercial Address: 1499 SW MARKET ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Mark Harding Failed Thursday, September 01, 2011

Inspection - Commercial

Corrective Action Required

1 MISC 1. SECURE AND SUPPORT MC IN WALL AND WITHIN12' OF

BOXES.

2. SECURE MC AT BOX.

3. SUPPORT AND ABOVE CEILING

INSTALL DAMPERS AS SHOW ON PLANS

Corrective Action Required

2 M303 EQUIPMENT

AND APPLIANCE

LOCATION

Corrective Action Required

3 M305 PIPING

SUPPORT

SUPPORT AND SECURE PLUMBING IN WALL. INSTALL PROTECTION PLATES PER CODE

SUPPORT PEX PER CODE, ABOVE CEIING AND IN WALL

Corrective Action Required

4 MISC

1. FIRE WALL-

NO INSPECTION ON SCREW PATTERN ON SHEETROCK-

RE-SCREW WALL FOR INSPECTION

PENETRATIONS IN WALL REAR CORRIDOR ABOCE CEILING

REPAIR PER CODE.

DO NOT MUD AND TAPE

REVISE PLANS FOR CHANGE IN CEILING SCHEDULE

NO ROCK COVERING I BEAM GIRTER OVER CEILING IN 1HR

WALL.

NEUTRAL AT SOUTH SUB PANEL LOOSE.

Comments: