## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20233168

Address: 2130 SW RUTHERFORD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Thursday, May 09, 2024

Residential

Corrective Action Required:

2 Miscellaneous 2130 SW Rutherford. All rough

Correction

garage anchor bolts needs to be in the middle 1/3 of sole plate

Garage trusses are not supported

Fire block the top of the chase in the great room Add joist hangers to the triple LVL's in the kitchen

Gaps at top plate at interior front door

Stair stringers needs to be supported at least 1 1/2 inches on the double 2x10

Brace is in the headroom of the attic access

Roof boots are not installed

Protect mechanical at sole and top plate with BOCA plates Top of HVAC chase upstairs needs to be fire blocked

2x10 support for stair landing is not installed along the south wall

14/2 wire is not fully installed in basement

## Comments: