



May 11, 2024

Kevin Higdon Construction  
Attn: Doug Slotter  
PO Box 847  
Lee's Summit, MO 64063

**RE: 806 NE Algonquin St., Lee's Summit, MO 64064**

Mr. Slotter,

At your request I have reviewed the as-repaired condition of the trusses identified in the recent rough-in inspection summary dated February 26, 2024 specifically relating to the following comment:

- "Engineer to address repair for damaged trusses above great room and above master closet \*\*Need truss repair detail for truss above living room. A 2x4 truss member was broken and torn out from the gusset joint to the top chord and replaced with a different 2x4. Engineer to address the fix for these; fix the other broken truss with 2x4x4 ft scabs per engineer"
  - *The above referenced trusses appear to have been repaired per the sealed drawings dated December 20, 2023 and February 6, 2024 provided by MiTek, Inc.*

Should you have any questions please do not hesitate to contact me.

Sincerely,

**Kurt Krasick, PE**  
**MAR Building Solutions**

1445 SE Broadway | Lee's Summit, MO 64081

Office: 816.272.5435 | Cell: 816.803.3737

[kurt@marbuildingsolutions.com](mailto:kurt@marbuildingsolutions.com) | [www.marbuildingsolutions.com](http://www.marbuildingsolutions.com)

