

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20230660
Address: 1950 SE BLUE PKWY, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection	Bobby Richest	Partial	Monday, May 06, 2024

Informational:

1	Misc	9-21-23 BR Erosion control is up and working order.
		10-2-23 BR Erosion control is up and working order.
		10-10-23 BR Erosion control is up and working order.
		10-16-23 BR Erosion control is up and working order.
		10-31-23 BR Erosion control is up and working order
		11-7-23 BR Erosion control is up and working order
		11-28-23 BR Erosion control is up working order
		12-5-23 BR Erosion control is up and working order
		12-19-23 BR Erosion control is up and working order
		12-28-23 BR Erosion control is up and working order
		1-4-24 BR Erosion control is up and working order

1-11-24 BR Erosion control is up and working order

1-23-24 BR Erosion control is up and working order

1-30-24 BR Erosion control is up and working order

2-2-24 BR Erosion control is up and working order

2-7-24 BR Erosion control is up and working order.

2-19-24 BR Erosion control is up and working order

2-29-24 BR Erosion control is up and working order

3-8-24 BR Erosion control is up and working order.

3-15-24 BR Erosion control is up and working order.

3-20-24 BR Erosion control is up and working order.

3-27-24 BR Erosion control is up and working order.

4-3-24 BR Erosion control is up and working order.

4-11-24 BR Erosion control is up and working order.

4-15-24 BR Erosion control is up and working order.

4-23-24 BR Erosion control is up and working order.

5-2-24 BR Erosion control is up and working order.

5-6-24 BR Erosion control is up and working order.

5-16-24 BR Erosion control is up and working order.

Comments: