

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20236672  
Address: 2759 SW HEARTLAND RD, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Mitchell Schwarz	Failed	Thursday, June 06, 2024

Corrective Action Required:

1 Misc

- missing 2x10 joist above garage
- block in between ceiling joist landing on rear garage wall
- fireblock hvac chase to ceiling space. (If using Unfaced insulation, it must be packed tightly and securely
- address cut floor joist above hvac chase
- top plate penetration S master bath wall
- 4 studs under lvl either end above wall in closet master
- tighten all anchor bolts in basement
- sister all over notched exterior wall studs in basement
- fire block vertically to horizontally every 10' in basement
- 

**Comments:**