CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20231105 Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Rated Assembly Inspection		Inspector: Robb Popp	Outcome:	Date:
			Partial	Thursday, June 06, 2024
Informati	ional:			
1	FIRST FLOOR	building A -Fire wall extension -Shear walls comple -1st and 2nd layer b -RC at units only -1st layer st firewal Building B:	ete ehind tubs Is	
		-Fire wall extensior -Firewall extension Building C: -Fire wall extensior	s at deck C/D ok for plywo	od
Informati	ional:			
2	SECOND FLOOR	-1st and 2nd layer a	l tubs ehind tubs lings units and coridoor ex t firewalls	ccept at firewall r walls and ceilng except at

	corridor ceiling from 200-208
	Building B: -Fire wall extension at decks B/C -Shear walls behind tubs -1st layer behind tubs -Firewall extensions at deck C/D ok for plywood
	Building C: -Fire wall extension at decks B/C
Corrective Action Required: 3 THIRD FLOOR	Building A: -Fire wall extension at decks A/B -Pre rock behind tubs 1st and 2nd Layer -RC at walls and ceilings units and corridor except at firewall -1st and 2nd layer at shear walls and fire walls -Screw pattern at all units and corridor walls and ceiling
	Building B: -Fire wall extension at decks B/C -Shear walls behind tubs -1st and second layer behind tubs -Firewall extensions at deck C/D ok for plywood -1st layer at firewalls
	Building C: -Fire wall extension at decks B/C
Informational: 4 FOURTH FLOOR	Building A: -Fire wall extension at decks A/B -1st and 2nd layer behind tubs at units -1st and 2nd layer at A/B separation wall at units -RC at units and corridor except at firewall -1st layer at units and corridor -Screw pattern at units and corridors and 2 hour walls
	Building B: -Complete except at firewall A/B
	Building C: -Fire wall extension at decks B/C -1st layer behind tubs -1st Layer at truss space separation wall C/D
Corrective Action Required:	*Building D: -1st Layer at truss space separation wall C/D
5 ELEVATOR 1 Corrective Action Required:	*Elevator 1 in building A -Complete except infill walls

6	STAIR TOWER 1	*Stair A building A -Shear wall nailing pattern at stair side of Stair A1 -1st and second layer walls at stair side, Stair A1 -2nd layer on east stair side screw pattern ok -1st layer at walls -RC, 1st,2nd and 3rd layer at ceiling -1st and 2nd layer walls at 4th floor **Install box extensions at ceiling boxes to be max 1/4" from face of rock			
Informational:					
7	STAIR TOWER 2	*Stair B in building B -Ceilng and walls complete at floors 2-4 -1st layer complete -Shear wall nailing complete			
Informational:					
8	STAIR TOWER 3	Stair 2B in builidng B -1st and 2nd layer stringer side only -1st layer all walls			
Informational:					
9	STAIR TOWER 4	*Stair D in building D -1st layer stringer side only			
Informational:					
10	STAIR TOWER 5	Stair E building E -Shear wall nailing pattern approved -1st and 2nc layer at stringer side only all floors			
Informational:					
11	ELEVATOR 2	Elevator 2 in building C: -Screw pattern at walls and ceiling complete -1st Layer in truss space			

Comments: