CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20240055 Address: 1020 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, July 02, 2024	
Corrective Action Required 1 Misc	: -Provide truss plans	for reinspection		
	Install missing stu -Secure all MC with -Seal top plate pene -Reattach truss brac -Install joist hanger	 -Install PAFs 12" oc to steel columns per plan' Install missing stud at NE corner-NAIL 12" oc -Secure all MC within 12" of boxes -Seal top plate penetrations -Reattach truss bracing to demising wall -Install joist hangers at RTU framing -Missing anchor bolts both sides of West door 		
	-OK UNIT E/F -Strap top plate lapped less than 48" -Secure mc -Seal plate penetrations UNITS G/H			

-Tie top plates together at steel columns

-Install PAFs 12" oc to columns

-Missing truss hangers and H2.5's at girder truss SW corner

-Seal plate penetrations

-Secure mc

-Reattach truss bracing

Comments: