CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20234377

Address: 3640 SW ARBORIDGE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Storm Sewer Construction

Inspection

Patrick Schonfeldt

Partial

Thursday, July 18, 2024

Informational:

1 Misc

 $\ensuremath{\text{6-7-24}}\xspace\,\text{PS}$ Contractor removing end section and headwall at existing end

section STA 0+00, storm line A

6-11-24 PS Headwall end section removed at existing storm 0+00, contractor

preparing site for install of junction box A-1

6-12-24 PS Contractor set junction box A-1

6-13-24 PS Contractor set junction box A-2 STA 0+78.94and set 60" HDPE from

A-1 STA 0+00 to A-2 STA 0+78.94

6-14-24 PS Contractor poured exterior collar and grouted existing box to A-1

junction box, excavating at 1+00

6-17-24 PS Contractor set HDPE storm line from A-2 STA 0+78.94 to STA 1+80.

PM contractor set HDPE from 1+80 to 2+80

6-18-24 PS Contractor set HDPE from 2+80 to A-4 junction box 3+38.59, pouring collar at A-2 junction 0+78.94. PM contractor poured inverts and set

lids at boxes A-4 and A-1

6-19-24 PS Contractor excavating for RCP install between existing storm box at arboridge to connect to junction A-2 0+78.94 PM contractor installing RCP at area listed above

6-20-24 PS Contractor completed both lines of RCP from existing box to A-2, collars poured at RCP at existing box and A-2 0+78.94

6-21-24 PS Contractor removed curb inlet from arbordidge as box A-3 deleted from project per 5-14 revision. storm line B connected to A-4 junction, collar poured at A-4

7-11-24 PS Contractor demo existing storm box at arboridge, excavating for install of curb inlet B-1, line B, STA 0+58.68 at road widening

7-18-24 PS Bair poured invert at junction box A-2

Comments: