CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242432

Address: 2502 SW TRACKER LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Tuesday, July 23, 2024

Residential

Corrective Action Required:

2 Misc No further inspections until erosion control is in compliance, address

overgrown vegetation

- -address over notched studs in garage for anchor bolts
- -primary closet exterior wall and garage wall top plates not tied together
- -boca plate to extent 2" past top plate at dwv in primary bath
- -provide proper slope for dwv above primary bath
- -missing nails in hangers above primary bed
- -fireblock fireplace to ceiling space
- -secure electrical to code in ceiling space
- -provide proper slope for dwv for bed 2 bath in ceiling
- -seal top plate penetrations at bed 2 entry
- -will check gb bracing screw pattern at time of drywall
- -address ceiling joist landing on foyer and all not load bearing
- -address over notched exterior wall studs for anchor bolts in basement to be
- -completed 10' fireblocking see wet bar area
- -seal penetrations in vertical to horizontal fireblocking
- -fireblock furr down ends in basement
- -seal top plate penetration at rear basement patio wall
- -secured electrical in ceiling space in basement

-fireblock top of furr out wall in basement bath

Comments: