



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	NEW CHINA BUFFET		
ADDRESS	711 SE M 291 HWY, LEES SUMMIT, MO 64063		
OWNER/OPERATOR NAME	MONUMENT EXTERIOR DESIGNS INC:	TELEPHONE	<NO PRIMARY PHONE>
ADDRESS	3816 N 99TH ST KANSAS CITY, KS 66109 Primary: <NO PRIMARY PHONE> Cell: (816) 914-3917 Jim / Dawn Hinkle @ 914-3917		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2. IN FDM	
3.	
4.	

LOSS REDUCTION TYPE

<input checked="" type="checkbox"/> Occupancy	<input type="checkbox"/> Semi-Annual	<input type="checkbox"/> Annual	<input type="checkbox"/> Life Safety	<input type="checkbox"/> Sprinkler	<input type="checkbox"/> Hazardous Material Permit
<input type="checkbox"/> Complaint	<input type="checkbox"/> Explosive Storage	<input type="checkbox"/> UST	<input type="checkbox"/> Post-Incident	<input type="checkbox"/> Open Burning	<input type="checkbox"/> Other
CLASS: A-2	Map#: 195M	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # PRCOM20110449

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection 1st Inspection 9/23/11 2nd Inspection 3rd Inspection 4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Not Ready	Friday, September 23, 2011
Corrective Action Required: 1 (1) ansul supression line needs to be plugged where a nozzel had been removed (2) seal all penetrations in the hood system (3) remove the dead blots and passage hardware from the west dining room exit door and the east kitchen exit door			
DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
September 23, 2011	Joe Dir	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	