## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRCOM20231105Address:800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Rated Assembly Inspection		Inspector: Robb Popp	Outcome: Partial	Date:
				Friday, August 02, 2024
Informa	tional:			
1	FIRST FLOOR	building A Complete		
		Building B:		
		*Submit 3rd party ap -Complete pool equ	proval for structural ste ipment room	el fireproofing
		Building C: -Fire wall extension:	s at deck B/C	
		-1st layer behind tub		
		<ul> <li>-1st and 2nd layer be</li> <li>-RC at units and corri</li> </ul>	idors except as noted:	
			ELEVATOR AND UNIT 1	19
		Building D:		
		-Fire wall extension	s at deck D/E	
		-Shear wall nailing p		
		-1st layer behind tub	05	
Informa				
2	SECOND FLOOR	Building A:		
		Complete		

	Building B: *Submit 3rd party approval for structural steel fireproofing
	Building C: -Fire wall extension at decks B/C -1st and 2nd layer behind tubs -1st layer at firewalls -RC complete except at elevator/ separation wall -1st layer at shear walls
	Building D: -Fire wall extensions at deck D/E
	Building D: -Shear wall nailing pattern -1st and 2nd layer behind tubs -1st layer at C/D firewall
Corrective Action Required: 3 THIRD FLOOR	Building A: Complete
	Building B: Copmlete
	Building C: -Fire wall extension at decks B/C -1st and 2nd layer behind tubs -1st layer at fire walls and shear walls -RC complete except at 324 -Screw pattern at units and corridors
	Building D: -Fire wall extensions at deck D/E -1st and 2nd ayer behind tubs -2nd layer at C/D firewall
Informational: 4 FOURTH FLOOR	Building A: Complete
	Building B: -Complete
	Building C: -Fire wall extension at decks B/C -1st layer behind tubs -1st Layer at truss space separation wall C/D -RC complete except at firewalls and corridor at 313 -Screw pattern at unit and corridor except at corridor framing outside of 313
	*Building D:

		-1st Layer at truss space separation wall C/D -1st and 2nd layer behind tubs		
Correctiv	e Action Required:	*Building E: -1st layer at truss space separation wall D/E		
5	ELEVATOR 1	*Elevator 1 in building A -Complete at inside 3 walls and ceiling -1st and 2nd ayer at inside of infill wall 1st and 4th floor -1st and 2nd layer at outside infill 1st-4th		
Correctiv	e Action Required:			
6	STAIR TOWER 1	*Stair A building A -Shear wall nailing pattern at stair side of Stair A1 -1st and second layer walls at stair side, Stair A1 -2nd layer on east stair side screw pattern ok -1st layer at walls -RC, 1st,2nd and 3rd layer at ceiling -1st and 2nd layer walls at 4th floor **Install box extensions at ceiling boxes to be max 1/4" from face of rock		
Informat	ional:			
7	STAIR TOWER 2	*Stair B in building B -Ceilng and walls complete at floors 2-4 -1st and 2nd layer complete -Shear wall nailing complete		
Informat	ional·			
8	STAIR TOWER 3	Stair 2B in builidng B -1st and 2nd layer stringer side only -1st layer all walls floors 1-4 -2nd layer walls and ceilngs at floors 1-3 -1st,2nd and 3rd layer at ceiling -Hat channel at ceiling		
Informat	ional:			
9	STAIR TOWER 4	*Stair D in building D -1st layer stringer side only		
Informat				
10	STAIR TOWER 5	Stair E building E -Shear wall nailing pattern approved -1st and 2nc layer at stringer side only all floors		
Informational:				
11	ELEVATOR 2	Elevator 2 in building C: -Screw pattern at walls and ceiling complete -1st layer at unit side		
Corrective Action Required:				
12	ELEVATOR 3	Elevator 3 in building D -1st and 2nd layer at truss space		

Comments: