## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRCOM20231105 Address: 800 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Monday, August 05, 2024
Informatio	onal:			
1	FIRST FLOOR	building A Complete		
		Building B: *Submit 3rd party approva -Complete pool equipmer	l for structural steel firepro nt room	ofing
		Building C: -Fire wall extensions at deck B/C -1st layer behind tub at firewall -1st and 2nd layer behind tubs -RC at units and corridors except as noted: **NOT COMPLETE AT ELEVATOR AND UNIT 119		
		Building D: -Fire wall extensions at de -Shear wall nailing pattern -1st layer behind tubs	-	
Informational:				
2	SECOND FLOOR	Building A: Complete		

	Building B: *Submit 3rd party approval for structural steel fireproofing Building C: -Fire wall extension at decks B/C -1st and 2nd layer behind tubs -1st layer at firewalls -RC complete except at elevator/ separation wall -1st layer at shear walls
	Building D: -Fire wall extensions at deck D/E
Corroctivo Action Poquirod	Building D: -Shear wall nailing pattern -1st and 2nd layer behind tubs -1st layer at C/D firewall
Corrective Action Required: 3 THIRD FLOOR	Building A: Complete
	Building B: Copmlete
	Building C: -Fire wall extension at decks B/C -1st and 2nd layer behind tubs -1st layer at fire walls and shear walls -RC complete except at 324 -Screw pattern at units and corridors
Informational:	Building D: -Fire wall extensions at deck D/E -1st and 2nd ayer behind tubs -2nd layer at C/D firewall
4 FOURTH FLOOR	Building A: Complete
	Building B: -Complete
	Building C: -Fire wall extension at decks B/C -1st layer behind tubs -1st Layer at truss space separation wall C/D -RC complete except at firewalls and corridor at 313 -Screw pattern at unit and corridor except at corridor framing outside of 313

		*Building D: -1st Layer at truss space separation wall C/D -1st and 2nd layer behind tubs		
		*Building E: -1st layer at truss space separation wall D/E		
Corrective Action Required:				
5	ELEVATOR 1	*Elevator 1 in building A -Complete at inside 3 walls and ceiling		
		-1st and 2nd ayer at inside of infill wall 1st and 4th floor		
		-1st and 2nd layer at outside infill 1st-4th		
Corrective Action Required:				
6	STAIR TOWER 1	*Stair A building A -Shear wall nailing pattern at stair side of Stair A1		
		-1st and second layer walls at stair side, Stair A1		
		-2nd layer on east stair side screw pattern ok		
		-1st layer at walls		
		-RC, 1st,2nd and 3rd layer at ceiling -1st and 2nd layer walls at 4th floor		
		**Install box extensions at ceiling boxes to be max 1/4" from face of rock		
Informati	ional:			
7	STAIR TOWER 2	*Stair B in building B		
		-Ceilng and walls complete at floors 2-4		
		-1st and 2nd layer complete -Shear wall nailing complete		
Informational:				
8	STAIR TOWER 3	Stair 2B in builidng B		
		-1st and 2nd layer stringer side only		
		-1st layer all walls floors 1-4 -2nd layer walls and ceilngs at floors 1-3		
		-1st,2nd and 3rd layer at ceiling		
		-Hat channel at ceiling		
Informati				
9	STAIR TOWER 4	*Stair D in building D		
Informati	ional:	-1st layer stringer side only		
10	STAIR TOWER 5	Stair E building E		
		-Shear wall nailing pattern approved		
1	a mali	-1st and 2nc layer at stringer side only all floors		
Informati 11	ELEVATOR 2	Elevator 2 in building C:		
11		-Screw pattern at walls and ceiling complete		
		-1st layer at unit side		
_		-1st Layer at corridor side all floors		
Corrective Action Required: 12 ELEVATOR 3 Elevator 3 in building D				
12	ELEVATUR 3	Elevator 3 in building D -1st and 2nd layer at truss space		

Comments: