

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRSUBD20230406  
Address: 1204 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Sediment Control (ESC) Inspection</b>	Nick Scott	Partial	Thursday, August 22, 2024

Informational:

1	Misc	5-16-23 Site visited and it appears that there is no erosion control set up. Please get the erosion control set up that is approved on the plans. If you have any question please call me 816-977-5652 Nick Scott 5-19-23 NS. ESC has not been set up yet. I talked to Jeff the developer and he said that they are working on someone to come out and put up ESC 10-25-23 NS Site visited and erosion control has failed I let the developer Jeff know and he had some out to fix it today. 12-18-23 NS Site Visited and no erosion control issues 12-20-23 NS Site Visited and no erosion control issues 12-22-23 NS Site Visited and no erosion control issues 12-28-23 NS Site Visited and no erosion control issues 1-3-24 NS Site Visited and no erosion control issues 1-23-24 NS Site Visited and no erosion control issues 2-28-24 NS Site Visited and no erosion control issues 3-29-24 NS Site Visited and no erosion control issues 4-18-24 NS Site Visited and no erosion control issues 4-30-24 NS Site Visited and no erosion control issues 6-28-24 NS Site Visited I talked to Jeff and he is going to get the site cleaned up and erosion control fixed. 7-25-24 NS Site Visited and still needs a little bit of clean up but for the most part it is clean and more erosion control has been set up.
---	------	---

8-8-24 NS Site Visited and crew where putting up more erosion control on  
8-7. It appears no problem from this rain so far.  
8-22-24 NS Site Visited and no erosion control issues

**Comments:**