

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241067
Address: 2087 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Not Ready	Wednesday, September 11, 2024

Corrective Action Required:

1	Miscellaneous Correction	-TIGHTEN ANCHOR BOLT BY SINGLE CAR BAY -Use approved materials for ceiling line fireblocking at fur down in garage-SEAL GAPS AND PENETRATIONS -Properly land and protect electrical and seal plate penetrations by stairs, also, only (2) nm cables are allowed per plate penetration-SEAL PENETRATIONS -missing multiple hangers and bracing on trusses throughout 2nd floor-WEB BRACING IS TO BE LOCATED AT THE MIDPOINT OF THE WEB -3 studs required at all exterior corners (see basement)-MISSING STUD AND CORNER NAILING PATTERN LEFT OF DOOR-NAIL 12" OC
---	-----------------------------	---

Comments: