CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242155

Address: 1632 SW BUCKTHORN ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Not Ready Thursday, September

Residential 12, 2024

Corrective Action Required:

1 Misc -seal bottom plate penetrations At dining area

-complete cspf nailing

-block wall space to ceiling space at great room(solid block sheathing breaks)

-will check GB bracing at time of install -seal low voltage penetrations in bed 2

-provid lateral bracing for trusses to throughout where missing(multiple

throughout)

-address A7 truss at top of stairs (no documentation uploaded to portal for

fix)

-fire block wall space into furr downs throughout basement

-missing stud at exterior wall corner NW basement (missing on N wall)

-missing anchor bolts for cspf rec room wall

-exterior nailing to be to plans

Comments: