CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Temporary Certificate of Occupancy

Permit #: PRRES20236605

Address: 3832 SW RAVENGATE PL, LEES SUMMIT, MO 64082

Inspected On: Tuesday, September 17, 2024

Inspected By: Development Center
Expiration Date: 9/17/2024 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Ready for Temp CO Friday, August 23, 2024

Residential

Informational:

1 Miscellaneous Sump pump extension is not installed

Correction -Sod and splash pads are not installed -Seal penetration in siding at gas line

-Exterior grading has not been completed for a plot plan inspection

-Plot plan must pass

This is the third TCO extension for this permit. Builder sent in another TCO extension form. A drive by inspection was done and this property has workers trying to finish up the exterior so an occupancy inspection can be

called in.

Occupancy Inspection - Codes Kyle Beard Ready for Temp CO Tuesday, July 23, 2024

Residential

2

Informational:

Miscellaneous Sump pump extension is not installed

Correction -Sod and splash pads are not installed

-Seal penetration in siding at gas line

220 SE Green Street | Lee's Summit, MO 64063 | 816.969.1200 | 816.969.1201 Fax | cityofLS.net/Development

-Exterior grading has not been completed for a plot plan inspection

-Plot plan must pass

Builder sent in a TCO extension form and stated that engineers are working

on the final plot grading.

Occupancy Inspection - CodesKyle BeardReady for Temp COThursday, June 27,Residential2024

Corrective Action Required:

2 Miscellaneous 3832 SW Ravengate. Occupancy (3)
Correction -Sump pump extension is not installed

-Sump pump extension is not installed
 -Sod and splash pads are not installed
 -Seal penetration in siding at gas line

-Exterior grading has not been completed for a plot plan inspection

-Plot plan must pass

Okay for TCO only

Occupancy Inspection - Codes Kyle Beard Ready for Temp CO Friday, May 17, 2024

Residential

Corrective Action Required:

2 Miscellaneous 3832 SW Ravengate. Occupancy (3)

Correction -Sump pump extension is not installed

-Sump pump extension is not installed -Sod and splash pads are not installed -Seal penetration in siding at gas line

-Exterior grading has not been completed for a plot plan inspection

-Plot plan must pass

Okay for TCO only

Comments: