

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20240373
Address: 3209 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Not Ready	Thursday, September 26, 2024

Corrective Action Required:

1	Misc	-fire block garage rear wall into furr down (seal gaps) -missing hold downs at trusses above garage-still missing 1 -address holes drilled closer than 2" to each other and top or bottom of floor joists above main floor(provide engineering for fix) -fire block hvac chases around great room windows -install roof boots -3studs at exterior wall corners see SW Corner-Screw all plies together with structural screws and nail sheathing
---	------	--

Comments: